

Annexure D

BUILDING SAFETY CERTIFICATE

NO. 3855

Date 05/12/2025

It is Certified that the existing building **SHREE SHANKARA SENIOR SECONDARY SCHOOL** Managed by Raipur Nair Samajam Regd. No. 564 (name of the building or premises) at P.H.No.40, Khasara No. 2/1 Part, Mouja- Urkura, Near Radio Station, Urkura Road, Ward No. 16, Urkura, Birgaon, Dist- Raipur (C.G.) (address) is having block(s)/Floor(s) as per details below.

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	03	03	03			

The building is owned/occupied by **SHREE SHANKARA SENIOR SECONDARY SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Municipal Corporation, Birgaon Name of Department/Govt.) on 23/06/2025 (date of inspection) in the presence of Shri Vipin Choubey (name and addresses of the Manager/Secretrary or his representative) and that the building/premises is fit occupancy for running School with effect from 24/06/2025 for a period of **One year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. As attached *structural stability Certificate done by Shri prashant Kumar Bani Structural Engineer Raipur (C.G.)*
2. —
3. —
4. —

Issued on/...../2025 at Birgaon, District- Raipur (C.G.) by * Strike out whichever is not applicable.

In case of block is more than six use separate sheet for detail.

Signature with Seal :- *[Signature]*
Name *[Signature]*
Designation :- *[Signature]*

[Signature]
Building Officer
Municipal Corporation, Birgaon
Dist- Raipur (C.G.)

[Signature]
Municipal Corporation
Birgaon
Dist- Raipur (C.G.)